

SCS ENGINEERS

December 22, 2016
File No. 23212007.04

Ms. Tracy Buchanan
Ohio EPA Southwest District Office
401 East Fifth Street
Dayton, Ohio 45402-2911

Subject: Village of St. Bernard Landfill
Contingency Probe Monitoring Results, December 22, 2016

Dear Ms. Buchanan:

Enclosed please find the results of the gas monitoring performed on behalf of the Village of St. Bernard at the closed St. Bernard Landfill on December 22, 2016.

No combustible gas concentrations above the compliance threshold were detected at MP-9 or MP-10. The sampling to terminate contingency monitoring at MP-9 and MP-10, as described in the EGMP, will continue.

Should you have any questions or comments, please contact the undersigned.

Sincerely,



Randall C. Mills, P.G.
Senior Project Professional
SCS ENGINEERS

cc: Chuck DeJonckheere, Hamilton County Public Health
Nick Schapman, GHD
John Estep, Mayor, Village of St. Bernard

Enclosures



James J. Walsh, P.E.
Principal
SCS ENGINEERS

Compliance Probe Monitoring Form for St. Bernard Landfill

Date: <u>12/22/16</u>	Sampler: <u>Randall Mills</u>
Instrument: <u>GEM 5000</u>	Weather: <u>few clouds, light breeze</u>
Calibration Prior to Sampling: <u>Yes</u>	Ambient Air Temperature (°F): <u>42</u>
Calibration Gas: <u>CH₄ 15%, CO₂ 15%, O₂ 4%</u>	Barometric Pressure (in Hg): <u>30.36</u>
Recalibration: <u>No</u>	Relative Humidity (%): <u>64</u>

Probe ID	Start Time	Stop Time	Gas Pressure (inches water)	Initial CH ₄ (% by Volume)	Sustained CH ₄ (% by Volume)	Depth to Water Level (feet below ground surface)	Depth to Top of Screen (feet below ground surface)	Open Screen [#] (feet)
MP-1							not known	
MP-7E							3	
MP-7H							2	
MP-8F							4	
MP-9	14:16	14:17	-0.02	0	0	7.32	2	5.3
MP-10	14:09	14:10	0.07	0	0	4.49	2	2.5
MP-16							2	
MP-17							2	
MP-9						--	--	--
MP-9						--	--	--
MP-10								

Notes:

Signature: Randall C. Mills

[#] A zero or negative value indicates that the probe is watered in.